Page 1

Work Order ID 60160

June 29, 2010 10:35:49 AM

Item ID:

D119-646-452

Revision ID:

Item Name:

Wearplates, RH, OEM

Start Date: Required Date: 7/07/10

6/28/10

Start Qty: 1.00 Req'd Qty: 1.00

Cust Item ID:

Customer:

Tool ID

Reference:

Approvals:

Process Plan:

QC:

Date: Date: **Tooling:**

0.00

Accept

SPC (Y/N):

Set Up/

Run Hours

Date: Date:

Tool # Plan

Code

Start

Setup

Run

Accept

Qty

Stop

Reject

Number

Reject

Qty.

Start

Stop

Insp.

Stamp

Sequence ID/ Work Center ID

Operation Description

Revision Nbr

Draw Nbr DSI 9526

Α

100

DOCUMENT CONTROL

Document Control

Memo

0.00

Photocopy blue file & type labels as per PPP D119-646-452 / DSI 9526 CHG

110

Packaging Packaging

Pick Kit

Memo

0.00

0.00

120

QC4- 100% Inspect kits for completeness

0.00

Quality Control

Memo

0.00

Scolutio

Work Order ID 60160 June 29, 2010 10:35:49 AM Item ID: D119-646-452 Accept Setup Start **Revision ID:** Stop Item Name: Wearplates, RH, OEM 6/28/10 Start Qty: 1.00 **Start Date:** Cust Item ID: Req'd Qty: 1.00 Required Date: 7/07/10 Customer: Reference: Run Start **Process Plan: Tooling:** Approvals: Date: Date: Stop QC: SPC (Y/N): Date: Date: Sequence ID/ Tool ID Reject Operation Set Up/ Tool # Plan Accept Work Center ID Description Code **Run Hours** Qty Qty. 130 0.00 Packaging 0.00 Packaging Memo Packaging Identify and pack for shipping as per PPP D119-646-452 / DSI 9526

PPP rev:

Memo

140

Quality Control

QC21- Final Inspection - Work Order Release

---- ()1007/6

Insp.

Stamp

MF 10-7-

Reject

Number

Picklist Print

Jugae 29, 2010 10:35:47 AM

Work Order ID: 60160

Parent Item:

Comments:

D119-646-452

Parent Item Name: Wearplates, RH, OEM

IPP Rev:A 10.06.25 new issue DD verf:EC



Start Date: 6/28/10

Start Qty: 1.00

Required Date: 7/07/10

Required Qty: 1.00

Component Item ID/ Item Name	Replacement Item ID	Mfg/ Purch	Bin Item	Primary Location	Last Location	Route Seq ID	Unit of Measure	Qty on Hand	Qty per Kit	Total Qty	Qty Issued	Date Issued	Status
Wearplate, RH Fwd		Manufactured	Ño			110	Each	0.0000		1 6	0/68		a
D4133-041 Wearplate, Mid		Manufactured	No			110	Each	0.0000		6	165		6
D4134-042 Wearplate, RH Aft		Manufactured	No	•	•	110	Each	0.0000			3/69		6
D4135-1 Wearpad		Manufactured	No			110	Each	0.0000	3	¹ 3 6	×167	6	
AELS-1032-130 INSERT		Purchased	No		·	110	Each	0.0000	20	²⁰ ,m)	14407	/p	7-959
AELS-1032-225		Purchased	No			110	Each I	0.0000	12	12	MIIO	765	10-7.7
10-1.89 11	32-225	,											:

Picklist Print

June 29, 2010 10:35:47 AM

Work Order ID: 60160

Parent Item:

D119-646-452

Parent Item Name: Wearplates, RH, OEM



Start Date: 6/28/10

Required Date: 7/07/10

Start Qty: 1.00

Required Qty: 1.00

AN3C5A

Purchased

No

No

110

Each

1,232.000

Location	<u>La</u>	oc Qty
ST350		1217
114330		11
114523		18
114808		188
		1000
ST351		15 .
113121		10
114108		5
	110	Each

Loc Code

Purchased NAS1149C0332R

Washer

Location	Loc Qty
ST297	5120
113524	10
113737	150
114341	36
115000 -	4924

Loc Code

5,120.000

Jugae 29, 2010 10:35:49 AM

Item ID:

D119-646-452

Revision ID:

Item Name:

Wearplates, RH, OEM

Start Date:

Reference:

Sequence ID/

Draw Nbr

Work Center ID

6/28/10

Start Oty: 1.00

Operation

Description

Revision Nbr

Required Date: 7/07/10

Approvals:

QC:

Process Plan:

Α

Reg'd Qty: 1.00

Date:

Date:

Tooling:

0.00

0.00

0.00

0.00

Photocopy blue file & type labels as per PPP D119-646-452 / DSI 9526 CHG.

Accept

SPC (Y/N):

Set Up/

Run Hours

Tool ID

Cust Item ID:

Customer:

Tool#

Code

Qty

Reject Otv

Run

Setup

Start

Stop

Start

Stop

Reject Number

Insp. Stamp

DSI 9526

100

DOCUMENT CONTROL

Memo

Document Control

110

Packaging

Packaging

Pick Kit

Memo

120

Quality Control

QC4-100% Inspect kits for completeness

Memo

0.00

0.00

Date:

Date:

Plan

Accept

CX 10/7/8



PARTS LIST

QTY -451	QTY -452	PART NUMBER	DESCRIPTION
Х		D119-646-451	WEARPLATE KIT, OEM LH
	X /	D119-646-452	WEARPLATE KIT, OEM RH
1		D4132-041	WEARPLATE, FWD LH
1		*D4132-3	GASKET (BONDED WITH 3M 1300/1300L)
	1	D4132-042 1	WEARPLATE, FWD RH
	1	*D4132-3	GASKET (BONDED WITH 3M 1300/1300L)
1	1	D4133-041 /	WEARPLATE, MID
1	1	*D4133-3	GASKET (BONDED WITH 3M 1300/1300L)
1		D4134-041	WEARPLATE, AFT
1		*D4134-3	GASKET (BONDED WITH 3M 1300/1300L)
	1	D4134-0427	WEARPLATE, AFT
	1	.D4134-31 "	GASKET (BONDED WITH 3M 1300/1300L)
3	3	D4135-1	WEARPAD
20	20	AELS-1032-130	INSERT
12	12	AELS-1032-225	INSERT
54	'54	AN3C5A	BOLT
54	54	NAS1149CO332R	WASHER

^{*} denotes that part is included in assembly above

<u>WEIGHT AND BALANCE</u>
The following weight and balance information is for the Dart D119-646-451/-452 kits only. The weight and balance of the wearplates removed are the responsibility of the installer.

		LONGITUDINAL		LATERAL	
Installation	Weight	Arm	Moment	Arm	Moment
D119-646-451	10.8 lb	117.7 in	1271 in lb	-39.4 in	-426 in lb
WEARPLATE KIT, LH	4.9 kg	2.99 m	14.7 m kg	-1.00 m	-4.9 m kg
D119-646-452	10.8 lb	117.7 in	1271 in lb	+39.4 in	+426 in lb
WEARPLATE KIT, RH	4.9 kg	2.99 m	14.7 m kg	+1.00 m	+4.9 m kg

DESIGN	9	DART AEROSPAC	E USA, INC		
DRAWN	97	PORT HADLOCK,			
CHECKED	#	DRAWING NO.	REV. A		
MFG. APPR.	N/A	DSI 9526	SHEET 2 OF 3		
APPROVED	***	TITLE	SCALE		
DE APPR.	#	OEM WEARPLATE KIT	NTS		
DATE 10.06.111 COPYRIGHT © 2010 BY DART AEROSPACE USA, INC. THIS DOCUMENT IS PRIVATE AND CONFIDENTIAL AND IS SUPPLED ON THE EXPRESS CONDITION THAT IT IS NOT TO BE USED FOR ANY PURPOSE OF COPYRED OF COMMINICATED TO ANY OTHER PRISON WITHOUT					